

SONY

Hi-Fi Products Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-491

No. 298

Subject: Display Board Change

Date: October 30, 1992


Symptom:
(**)

The display board layout has been changed along with IC401 which has been changed to a DIP package type component.

Solution:

Refer to layout drawing below when troubleshooting and to order IC401, refer to part number shown in chart:

REFERENCE	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
IC401	IC uPD75212ACW-A23	8-752-817-41	8-759-058-72



(Continued)

Reference: FPR N1744

PRINTED IN U.S.A.
CSA-131092-3

CSA-13 CD Player

CDP-491
DISPLAY BOARD

