

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-FX6/-FX1010/-K555/-555ES

No. 185


Subject: New Motor Does Not Turn

Date: April 12, 1991

Symptom:
(61)

After replacing the capstan motor M2 (P/N X-3575-308-0), the motor does not move upon power up.

Solution: A solder bridge is missing. Replacing the bridge will solve the problem.



Tape Deck

CSA-13