Model-5 1934 IF 460 K.C



The Model EF takes the place of the EB dynamotor. The cable connection between the Vibrator and the Model 6F completes the installation of the Vibrator.

MODEL EF VIBRATOR



NOTE.—The first condensers (30-4017) were made up having five sections. The .1 mfd. section has now been removed from the can and this section replaced with a .006 mfd. condenser (Part No. 30-1001). This condenser is located in the chassis adjacent to the grid terminal of the 41 tube socket.



Model-10

1933-34 IF 260 KC.

DATA SHEET

PRINTED IN CANADA

COURTESY PHILCO-17 PRODUCTS LTD.