SONY

Hi-Fi Products
# Service Bulletin

**Sony Service Company** - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

**Model:** TC-WR510 **No.198**

**Subject:** Part Number Correction - RV-301 Record Balance Control **Date:** June 26, 1991

**Symptom:** ( ** ) The part number listed on page 18 of the service manual for RV-301, Recording Balance Control, is incorrect.

**Solution:** Please note the correct part number shown below.

| Reference Number | Description | Part Number | |
|---|---|---|---|
| | | Incorrect | Correct |
| RV-301 | Recording Balance Control | 1-238-835-11 | 1-238-683-11 |

[DISPLAY BOARD]




CSA-13 Tape Deck



PRINTED IN U.S.A.
CSA-13691-2