








Base View



Top View

CRITICAL LEAD DRESS

When performing service do not disturb or alter the placement of components or the routing of leads.

Avoid placing components or leads near R16, the 270 ohm, 7 watt, wire wound output cathode resistor

or R21, the 3300 ohms, 2 watt B+ filter resistor. Both of these units operate at a high temperature and may damage any part in contact with them.