

CDP-501/501ES

SERVICE MANUAL

AEP Model

No. 1
April, 1984

SUPPLEMENT


File this supplement with the service manual.

SUBJECT: Part Number Changes on AUDIO Board to improve Frequency Response.

1. Parts List:

<u>No.</u>	<u>Part No.</u>		<u>Description</u>
	Former	New	
527	♣A-4651-011-A	♣A-4651-029-A	(AEP)MOUNTED PCB, AUDIO AMP
C533, C536, C633, C636	1-104-235-00	1-104-250-00	(AEP)POLYSTYRENE 820PF, ±2% 125V
F501, F601	1-464-299-00	1-464-299-22	(AEP)UNIT, LOWPASS FILTER

COMPACT DISC PLAYER
SONY®



Sony Corporation