

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C20/C26/C30

No. 63

Subject: Missing Part Number


Date: February 23, 1989

Symptom:
(**)

The part number for the damper is not listed on page 18 of the service manual.

Solution: Please add the following part number to your service manual:

Description	Part Number
Damper	4-924-422-01



CSA-13 Compact Disc

Reference: RCP

PRINTED IN U.S.A.
CSA-13189-6