

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C211/C215/C315

No. 336

Subject: Part Number Addition: Plastic Window For Front Panel


Date: April 19, 1993

Symptom:
(**)

The front panel (ref. 2) is not shipped from the National Parts Center with the plastic window installed.

Solution: Order the plastic window as shown below:

REF	DESCRIPTION	PART NUMBER
-	COVER, INDICATION PANEL	4-944-146-01



CSA-13 CD Player



PRINTED ON RECYCLED PAPER

Reference: FPR-O1161
Autoflagged - NO

PRINTED IN U.S.A.
CSA-13493-1