

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C40/50

No. 31


Subject: Part Number Missing - Bracket;
Optical Assembly

Date: September 19, 1988

Symptom:
(**)

The Bracket; Optical Assembly is shown on page 20 of the service manual. However, it is not referenced or listed in the parts list. The part and part number are shown below:

Solution:



Compact Disc

CSA-13