

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C505/C35/C201/C205/C305

No.135R1

Subject: Part Number Of Flex Cable - CNJ301 Date: January 7, 1991



This Service Bulletin Supersedes Service Bulletin No. 135

Symptom:
(**)

The part number of the Flex Cable (CNJ301) is not listed in the service manual.

Solution: Please update your service manual with the part number listed below:

Ref. No.	Description	Part Number
CNJ301	Flex Cable	1-535-847-11



CSA-13 Compact Disc