

Date	Ref. No.	Model	
21.12.05	03HA035R2	STR-VA555ES	HA
Subject			IRIS
No AUTOBETICAL Mode [REVISION 2]			C17X

Confidential

SYMPTOM

No correct AUTOBETICAL station storage.

CAUSE

Malfunctioning software.

SOLUTION

Download the attachment "**V175.zip**" to your PC. Extract the zip file to a dedicated folder, and after reading the "VA555ES_readme.doc" installation manual, perform the firmware upgrade.