

SONY

Hi-Fi Products Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-H3600

No. 262


Subject: Extension Cables To Facilitate Troubleshooting

Date: March 31, 1992

Symptom:
(**) It is impossible to troubleshoot the output circuit without extension cables.

Solution: Please order the following extension cables:

EXTENSION CABLE PART NUMBER	PURPOSE
J-8000-033-A	FOR CONNECTING POWER AMP BOARD CN801 TO CONNECTOR (A) BOARD CN812
J-8000-032-A	FOR CONNECTING POWER AMP BOARD CN802 TO CONNECTOR (B) BOARD CN821



Reference: FPR N0362

PRINTED IN U.S.A.
CSA13392-10

CSA-13 Amplifier