Professional Audio Products Technical Bulletin 89–034

Sony Technology and Engineering Operation Training and Publications 677 River Oaks Pkwy, San Jose, California 95134

Date: May, 1989

Subject: ADDITIONAL REPLACEMENT PART

AVAILABILITY

Model: BTA-27

Serial No: ALL

DESCRIPTION

The following BTA-27 service parts are now available through the Sony Kansas City National Parts Center. Figure 1 shows the newly added parts.

PARTS REQUIRED

Part No.	Description	SP	Qty.
7–682–545–09	⊕ B3x4	s	1
A-4539-052-A	Bracket Assembly	0	1
2-379-903-03	Leather Case	0	1




Figure 1