

TCM-959T

SONY® SERVICE MANUAL

US Model
Canadian Model
AEP Model
E Model

CORRECTION-1

Correct your service manual as shown below.

 : indicates corrected portion.
Page 5.

AM IF ADJUSTMENT	
Adjust for a maximum reading on VTVM.	
T3	
 455kHz	

AM FREQUENCY COVERAGE ADJUSTMENT	
Adjust for a maximum reading on VTVM.	
L4	CT3 
520kHz	1,780kHz (1,680kHz)

AM TRACKING ADJUSTMENT	
Adjust for a maximum reading on VTVM.	
L3	CT4 
600kHz	1,500kHz (1,400kHz)

FM FREQUENCY COVERAGE ADJUSTMENT	
Adjust for a maximum reading on VTVM.	
L2	CT1 
86.5MHz <87.0MHz> (87.35MHz)	109.5MHz <108.3MHz> (107.8MHz)

FM TRACKING ADJUSTMENT	
Adjust for a maximum reading on VTVM.	
L1	CT2 
86.5MHz <87.0MHz> (87.35MHz)	109.5MHz <108.3MHz> (107.8MHz)

