

TC-WA8ES/WR765S

SONY SERVICE MANUAL

US Model
Canadian Model
TC-WA8ES

AEP Model
E Model
Australian Model
TC-WR765S


SUPPLEMENT-1

File this Supplement with the Service Manual.

Subject : CHANGE OF HEADPHONE BOARD
(1-656-360-11 ⇒ 1-656-360-14)

(ECN-TC500627)

● LOCATION 1-J, 1-2



Former (1-656-360-11)					New (1-656-360-14)				
Ref. No.	Part No.	Description			Part No.	Description			
C303	1-162-294-31	CERAMIC	0.001uF	10% 50V	1-162-294-31	CERAMIC	0.001uF	10% 50V	(TC-WR765S: AEP, German)
C403	1-162-294-31	CERAMIC	0.001uF	10% 50V	1-162-294-31	CERAMIC	0.001uF	10% 50V	(TC-WR765S: AEP, German)
ECP1					1-765-469-11	LEAD WITH CONNECTOR	(TC-WR765S: AEP, German)		

Sony Corporation
Consumer A&V Products Company
Home A&V Products Div.

9-960-167-81

English
95H020467-1
Printed in Japan
© 1995.8
Published by Home A&V Products Div.
Quality Engineering Dept.