TC-WR770/WR875

SONY. SERVICE MANUAL

US Model TC-WR875 AEP Model UK Model TC-WR770

CORRECTION-1

Correct your service manual as shown below.

: indicates corrected portion.

Page	INCORRECT	CORRECT
	Playback Level Adjustment :	Playback Level Adjustment
	:	:
	:	:
10	:	:
	Adjustment limits: LINE OUT level: -20±0.5dB(73.2 — 83.0mV)	Adjustment limits: LINE OUT level: -7.8±0.5dB(0.298 — 0.334V)